



- File > Open Construction Lines > bulk.dxf

Import DXF Mine Plans




- CAD > Build > FFLoop 
- CAD > Snap > Trace CLoop Snap 

Start the “FFLoop” routine and set the “Trace CLoop Snap” mode




• CAD > Snap > Trace CLoop 

Set the desired element width (10) by picking the “Trace CLoop Snap” mode a 2nd time




- The entire line will automatically be traced
- Points will be generated at 10m intervals

Pick one point on the construction line




• CAD > Build > Extrude/Offset 

Pick the “Extrude” command (0,0,5)



• Entity Properties Build

Pick the “Build” command



This completes construction of the drift on this level